C.L. "BUTCH" OTTER - Governor RICHARD M, ARMSTRONG - Director

> DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-033 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

March 6, 2007

Marilyn Sheppard, Administrator Ivy Gardens Assisted Living 1107 15th Ave South Nampa, ID 83651

License #: RC-754

Dear Ms. Sheppard:

On January 18, 2007, a life safety code survey was conducted at Ivy Gardens Assisted Living. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

EM/slc



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

February 2, 2007

Marilyn Sheppard, Administrator Ivy Gardens Assisted Living 1107 15th Ave South Nampa, ID 83651

Dear Ms. Sheppard:

On January 18, 2007, a life safety code survey was conducted at Ivy Gardens Assisted Living. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by February 17, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

(X3) DATE SURVEY COMPLETED STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: (X2) MULTIPLE CONSTRUCTION 01 - ENTIRE BUILDING A. BUILDING B. WING 01/18/2007 13R754

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

			1107 15TH AVE SOUTH NAMPA, ID 83651			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIE (EACH DEFICIENCY MUST BE PRECEDED BY REGULATORY OR LSC IDENTIFYING INFORM	FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
R 000	Initial Comments The facility was found to be in substanticompliance with the fire and life safety requirements of the Rules for Residenti Assisted Living Facilities in Idaho. No deficiencies were cited during the standfire/life safety survey conducted on Jan 2007. The surveyor conducting the survey was	ial or core dard uary 18,	R 000			
	Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety & Construction	Program				
	acility Standards				in a constant of the constant	

Bureau of Facility Standards

TITLE

(X6) DATE

FMWO21



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

Facility Name		Physical Address	Phone Number						
Ivy Gardens A	ssited Living	1107 15th Arnu South	466 7330 ZIP Code						
Administrator	eneral	City	ZIP Code						
Marilyn Shepp. Survey Team Leader	ard :	City Vampa Survey Type	83651						
		Survey Type	Survey Date						
Ene mudle		Fir / Life Safely	Jan 18,2007						
NON-CORE ISSUES									
ITEM RULE #		DESCRIPTION	DATE RESOLVED						
1 16.03.22.250,15	(all System: A	Call System had not been instale	led in york of						
	Ma facility I	here is no interior that would be	approved su						
	prior to Janu	any 2016.							
2 16.03.72.905,016	Electrical dying	omet: An extension cond was pour	cring a 7/24/07						
	Treezer in the	shed in the back yard.							
3 16.03.22.750,01	Fire Drills:	Drills were not decumented for the	e fair 2/28/07						
	quarter of 200	and the same of th							
4 16.03.22.750.03	Furnace ingo	tin: There was no report mainto	mined on 2/26/67						
		the funnee had a full gunal							
	in 200 Ca.		ž						
5 16.03.72.750.056		documentation of stell conduction	y monthly 2/26/47						
	Cents of the	for along system.							
		<i>3</i>							
Response Required Date	Signature of Facility Representative								
C1162007	N 1200	- X6 - 02 - 1							